

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

October 17, 2013

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 13-0207

ACHD Reference Number: N/A

Sulfur Plant

USS Clairton Works

FOREIVED

OCT 25 2013

3AP20

Dear Gail Eddings,

The attached form terminates the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Schumacher Thomas E.

Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 13-0207 <u>Termination</u>
ACHD Reference Number: N/A

- 2. Date & Time of Breakdown: Date: 10/15/13 Time: 1630 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: Sulfur Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The 101J sulfur plant vacuum axi is unavailable for service. The cause of the axi outage is under investigation. The 101J Axi is a redundant piece of equipment. The spare C658 Axi will carry the full load. Sulfur Plant performance will not be affected and emissions will not increase due to this work.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The spare C658 Axi will carry the full load. No
 environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted). $\ensuremath{\mathbb{N}/\mathbb{A}}$
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 The 101J Axi seized during operation and the restriction was manually released. The spare C658 Axi carried the full gas flow to the plant.
- 10. Facility back in operation Date: 10/16/13 Time: 1900 hours

Reviewed	by (((1: n /), (1:1))		Date	16-17-13		
		M. Davis	6			
	Senior	Environmenta	l Control	Engineer	Phone:	412-233-1015



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

October 17, 2013

OCT 25 2013

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 13-0208

ACHD Reference Number: 16411 #3 Battery Igniter Flare

USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Thomas É. Schumacher

Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 13-0208 ACHD Reference Number: 16411
- 2. Date & Time of Breakdown: Date: 10/17/13 Time: 0930 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: #3 Battery Igniter Flare
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The #3 Battery Igniter Flare was temporarily unavailable for service to perform routine maintenance.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 No environmental impact.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A.
 - C. Amount of each type emitted (or likely to be emitted). N/A.
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The Igniter Flare was available for service upon completion of the task.
- 10. Facility back in operation Date: 10/17/13 Time: 0950 hours

Reviewed	hy	alen h. Davis	Date 10-17-13	
Nevrewed	Dy	C1 000 /11 : 31003	5000 10 11 17	

Coleen M. Davis

Senior Environmental Control Engineer Phone: 412-233-1015



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

October 16, 2013

RECEIVED OCT 25 2013

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 13-0207

ACHD Reference Number: N/A

Sulfur Plant USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Thomas E. Schumacher

Plant Manager Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 13-0207 ACHD Reference Number: N/A

- 2. Date & Time of Breakdown: Date: 10/15/13 Time: 1630 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: Sulfur Plant
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The 101J sulfur plant vacuum axi is unavailable for service. The cause of the axi outage is under investigation. The 101J Axi is a redundant piece of equipment. The spare C658 Axi will carry the full load. Sulfur Plant performance will not be affected and emissions will not increase due to this work.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 The spare C658 Axi will carry the full load. No
 environmental impact is expected.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A No environmental impact is expected.
 - C. Amount of each type emitted (or likely to be emitted). N/A
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
 The spare C658 Axi will carry the full gas flow to the plant.
- 10. Facility back in operation Date: Time: hours

Reviewed	by Alan In Davis	Date 10-16-13
	Coleen M. Davis	

Senior Environmental Control Engineer Phone: 412-233-1015